

# S6 GSM/PCN

## Level 2.5

# Repair Documentation

V1.4

**Table of Contents:**

**1 RF CONNECTOR**.....**3**

**2 EXCHANGE OF EXTERNAL CONNECTOR**.....**6**

**3 1A FUSE**.....**10**

**4 RINGER**.....**13**

**5 ANNEX**.....**16**

## 1RF Connector

### 1.1 Affected Units

1.1.1 Type: S6 GSM / PCN

1.1.2 Affected IMEIs / Date Codes: All / All

1.1.3 Affected SW-Versions: All

1.1.4 Fault Code for LSO reporting: 3RFC

### 1.2 Fault Description

#### 1.2.1 Fault Symptoms for customers:

Customers experience a low Rx sensitivity of the handset, having problems registering to the network and making calls.

#### 1.2.2 Fault Symptom on GSM-Tester:

The GSM-Tester will show a low Tx-Power only on the *internal* antenna (aerial coupler measurement!).

### 1.3 Priority:

- ..... Mandatory
- ..... Repair
- ..... Optional
- ..... Not Yet Defined

## 1.4 Repair Documentation

### 1.4.1 Description of procedure:

#### 1.4.1.1 Diagnosis

Visually check the status of the antenna connector. Look for a bent contact or dry soldering joint.

#### 1.4.1.2 Repair by component change

Use hot air blower to remove defective connector.

Resolder new connector afterwards.  
Pin 1 is the RF pin, pins 2 and 3 are ground.

#### 1.4.1.3 Repair by SW-Booting

Not possible!

#### 1.4.1.4 Test

Retest handset after repair.

### 1.4.2 List of needed material

#### 1.4.2.1 Components

Connector X751  
Part-Number: L24859-Z1359-A24

#### 1.4.2.2 Jigs and Tools

Soldering Iron  
Hot Air Blower

#### 1.4.2.3 Special Tools

None

### 1.4.2.4 Working materials

Desolder Wick / Braid  
Solder  
Flux

### 1.4.3 Drawings

Figure 1: S6 Board RF Connector Side




Figure 2: S6 RF Connector (X751) Placement (Top View)

## 2 Exchange of External Connector

### 2.1 Affected Units

2.1.1 Type: S6 GSM / PCN

2.1.2 Affected IMEIs / Date Codes: All / All

2.1.3 Affected SW-Versions: All

2.1.4 Fault Code for LSO reporting 3MOC

### 2.2 Fault Description

#### 2.2.1 Fault Symptoms for customers:

Customers are unable to charge the battery, since the charging pin is broken/missing

Network search

Connector is physically damaged

#### 2.2.2 Fault Symptom on GSM-Tester:

Power problems on the external and internal antenna

Location update problems on external and internal antenna

### 2.3 Priority:

- ..... Mandatory
- ..... Repair
- ..... Optional
- ..... Not Yet Defined

## 2.4 Repair Documentation

### 2.4.1 Description of procedure:

#### 2.4.1.1 Diagnosis

There is a mechanical switch in the bottom connector which switches between the external and internal antenna of the handset.

The switch is located behind pins 23, 24, 25 and 26, while 23 and 26 are ground connections and 24 and 25 are RF connections.

Dry joints at these pins will interrupt the RF connection both to the internal and external antenna of the handset, resulting in „network search“ problems.

See figure 2 for the location of the pins!

Furthermore if the connector is physically damaged (missing charging pin), it will have to be replaced.

#### 2.4.1.2 Repair by component change

Use hot air blower to remove defective connector.

**Attention:** Make sure that the neighbouring components are not exposed to heat!

Clean solder pads with desoldering wick afterwards.

Fix new connector and solder ground connections first (Pins 18, 20, 21, 22, 23 and 26 in figure 2).

Then the other connections are soldered, using only very little flux.

It is highly recommended to use a microscope during the work!

If too much flux is used, the connector will not work anymore!

#### 2.4.1.3 Repair by SW-Booting

Not possible!

#### 2.4.1.4 Test

After the connector change check solder joints with a microscope.

Check charging functionality by connecting a travel charger to charging plug. If the connection is right, the charging symbol must appear on the

handset display (make sure that a battery is inserted!).

### 2.4.2 List of needed material

#### 2.4.2.1 Components

External Connector  
Part-Number: L36851-Z1351-A70

#### 2.4.2.2 Jigs and Tools

Soldering Iron  
Hot Air Blower

#### 2.4.2.3 Special Tools

None

#### 2.4.2.4 Working materials

Desolder Wick / Braid  
Solder  
Flux

### 2.4.3 Drawings

Figure 1: S6 Board External Connector Side







Figure 2: S6 External Connector (X203) Placement (Top View)



## 31A Fuse

### 3.1 Affected Units

3.1.1 Type: S6 GSM / PCN

3.1.2 Affected IMEIs / Date Codes: All / All

3.1.3 Affected SW-Versions: All

3.1.4 Fault Code for LSO reporting 3FU1

### 3.2 Fault Description

#### 3.2.1 Fault Symptoms for customers:

Customers are unable to charge the battery.

#### 3.2.2 Fault Symptom on GSM-Tester:

This fault cannot be detected with a GSM-Tester.

### 3.3 Priority:

- ..... Mandatory
- ..... Repair
- ..... Optional
- ..... Not Yet Defined

### **3.4 Repair Documentation**

#### **3.4.1 Description of procedure:**

##### **3.4.1.1 Diagnosis**

If the customer connects a charger which delivers a current  $> 1$  ampere, the fuse F201 will blow to protect the charging curcuitry. The Siemens chargers have a current limit of 700mA.

The status of F201 can easily be checked with a multimeter. If the resistance is infinit, the fuse is blown.

##### **3.4.1.2 Repair by component change**

Use soldering iron to remove defective fuse.

Resolder new fuse afterwards.

##### **3.4.1.3 Repair by SW-Booting**

Not possible!

##### **3.4.1.4 Test**

Check resistance of fuse ( $< 1$  Ohm) and check charging functionality afterwards by connecting a travel charger to complete phone. If you have a battery inserted, the charging symbol must be visible on the handset display.

### **3.4.2 List of needed material**

#### **3.4.2.1 Components**

Fuse F201 (1A)  
Part-Number: L36145-A820-Y7

### 3.4.2.2 Jigs and Tools

Soldering Iron

### 3.4.2.3 Special Tools

None

### 3.4.2.4 Working materials

Desolder Wick / Braid  
Solder  
Flux

### 3.4.3 Drawings





Figure 2: S6 Fuse (F201) Placement / Top View

## 4Ringer

### 4.1 Affected Units

4.1.1 Type: S6 GSM / PCN MMI

4.1.2 Affected IMEIs / Date Codes: All / All

4.1.3 Affected SW-Versions: All

4.1.4 Fault Code for LSO reporting 3RIN

### 4.2 Fault Description

#### 4.2.1 Fault Symptoms for customers:

Ringer tone is not audible or distorted.

#### 4.2.2 Fault Symptom on GSM-Tester:

Ringer test fails.

### 4.3 Priority:

- ..... Mandatory
- ..... Repair
- ..... Optional
- ..... Not Yet Defined

**4.4 Repair Documentation****4.4.1 Description of procedure:****4.4.1.1 Diagnosis**

See symptoms above

**4.4.1.2 Repair by component change**

Use soldering desoldering braid to remove defective ringer.

Resolder new ringer afterwards.

**4.4.1.3 Repair by SW-Booting**

Not possible!

**4.4.1.4 Test**

Retest handset.

**4.4.2 List of needed material****4.4.2.1 Components**

Ringer  
Part-Number: L36178-Z2-C16

**4.4.2.2 Jigs and Tools**

Soldering Iron  
Desoldering braid

**4.4.2.3 Special Tools**

None

**4.4.2.4 Working materials**

Desolder Wick / Braid  
Solder  
Flux

## 5ANNEX

### 5.1 Dry joints / soldering problems

The S6 GSM/PCN, S6Classic GSM/PCN and the E10 have a mechanical antenna-switch in the bottom connector (molex connector).


As a consequence of this a lot of RF problems will come up, if the soldering is bad. Due to the difficult production soldering process of the bottom connectors, a relatively high percentage of handsets could be affected by this problem.

RF problems are for example a low or completely missing output power, or a missing RX-sensitivity.

In order to analyze the situation, please use the diagram below.

*Note: The S10 / S11 does not have a mechanical switch inside the molex connector, so dry joints will only affect the external handset antenna.*





\* Internal antenna problems could also be caused by the display module. Make sure that you test the board with a reference display module.