

Service Information

1997-01-18

**Café Roma Therm
HD 7262/F**

DAP 138

Domestic Appliances and Personal Care

Reference is made to Service Manual: Café Roma Therm HD 7262/F
4822 729 21718

To prevent the pump from furring up with scale too quickly, it has been decided to use a 1000W pump instead of a 1200W one as mentioned in the Service Manual of the HD 7262/F coffeemaker Roma Therm.

This means that service item 12: 4822 259 20435 Pump unit 1200W
will change into 4822 259 20445 Pump unit 1000W