

**SONY**

RGB/Video Monitors  
**Service Bulletin**

**CSI-112**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** PVM-1344Q, PVM-1944Q, PVM-1341, No. 8  
PVM-1342Q, PVM-1343MD, PVM-1942Q,  
PVM-1943MD, PVM-1340

**Subject:** CP-401 Part Number Missing

**Date:** January 21, 1994

**Symptom:**  
(\*\*)

What is the Part Number for the CP-401 Module or the individual zener diodes making up the Module ?

**Solution:**

Please add the following part number to the Service Manual.

REF	DESCRIPTION	PART NUMBER
CP-401	ZENER BLOCK (3 X RD13ES-B2)	1-232-346-00
	INDIVIDUAL ZENER DIODES RD13ES-B2	8-719-110-36

