

# Service Information

1996-8-8

HD4500 HD4501  
HD4502 HD4503


DAP128

## Domestic Appliances and Personal Care

Reference is made to Service Manual 4822 729 21635

IEC version only :

If in these version thermal fuse 1 ( Item 13, attached to the bottom ) need replacement, fix a new fuse above fuse 2 and tie with Nylon cables. Do not fix it to the original position.



SERVICE

SERVICE

SERVICE

4822 729 21696

PCS 87 499