

Service Information

1997-10-22

HR 6353	HR 6371
HR 6374	HR 6377
HR 6395	HR 6399

DAP153

Domestic Appliances and Personal Care

The **/B version** has been provided with a different motor than the A/ version. Contrary to the specifications in the service manuals 4822 729 21387 and 4822 729 21518, the following items must be used for the **/B version**.

The spares for the **/B version** are the following items:

33	4822 361 10961 4822 361 10998	Motor 220V Motor 240V
40	Not available	Carbon brush
34+38	4822 466 11759	Motor suspension parts
–	Not available	wiring

If the **dust cover** of the **/B version item (10)** must be replaced, an **additional hole** of \varnothing 7 mm, matching the hole in the original part, must be made in the inner lid to meet the temperature requirements.